

Ferrari 7 Fingerprint Schematic EC Tracking Record (For SA) Jun.25 , 2007

EC #/ Page / Description / Part Affected

- EC SA01/01/ Change X1 P/N from "82.30006.211" to "82.30006.271", the reason is for cost down.
- EC SA02/01/ Change ESD diode package and reserve D1 type, the reason is for sourcer recommend and cost down.
- EC SA03/01/ Add 0 ohm resistor, the reason is for ESD fail.

*Adjusted for optimum
fingerdetect performance*

