





R1.1 on 090413 for EMI






UX30 IO BD R1.1 Change List

- 1. Remove R9901 and change JACK_SW# to J9901.4 for Headset detect error

UX30 IO BD R1.2 Change List

- 1. Change J9803 from 12G183402207 to 12G18340200T for cost down on Page 1
- 2. Change J9901 Pin 4 , 5 connection define on Page 2



Title : HISTORY

<OrgName>

Engineer: Uei Lee & Hacken

Size

B

Project Name

UX30 IO BD

Rev

1.2

Date: Tuesday, April 28, 2009

Sheet 3 of 3